Service Campaign Bulletin

TO:

SUBJECT:

Service Campaign Bulletin

Service Campaign Bulletin

An authorized Mercedes-Benz & Freightliner Sprinter dealer will provide and program two additional vehicle keys

MBAG, the manufacturer of Mercedes-Benz & Freightliner Sprinter Vans, has determined that certain Sprinter vehicles were delivered with two electronic keys, and two mechanical keys as a substitute

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 3,008 vehicles are affected.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Model 907, 910

with code FZ9 (Two additional master keys)

Operation no. of the operation texts or standard texts and flat rates

Category	Op. no.	Operation text	Time	Acc. no.	Code
L	02 1254	Operations: Program 2 additional keys	0.4hrs	80 910 53	VS3VEHIKE
					Υ

The mechanical parts (key bits) of the two additional keys were handed over to the customer previously when the vehicle was delivered.

	T	1	T
Topical note	Notes on carrying out repair work in the vehicle interior		AH68.00-N-0001-01S
4	Check		
1	Check, whether the vehicle is affected by the measure.	Affected vehicles: Program 2 additional keys (code: VS3VEHIKEY, acc. no.: 80 910 53) Model 907.### ## as of 034804 up to 314021 with code FZ9 (Two additional master keys)	SM80.35-D-0002-01AAA
		Affected vehicles: Program 2 additional keys (code: VS3VEHIKEY, acc. no.: 80 910 53) Model 910.### ## as of 039102 up to 318064 with code FZ9 (Two additional master keys) i For authorized Mercedes-Benz service partners, only the entry in the Extended VEGA Application (EVA) system, in the "Current" tab, is decisive. An additional test of the affected vehicles in the workshop information system (WIS) or vehicle list is thereby not necessary.	SM80.35-D-0002-01AAB
	Programming		
2	Connect diagnostic system.		
⊯ AD		It is absolutely essential to precisely follow the operation steps as described in the vehicle diagnosis system.	AD00.00-D-2000-06TS

3	Connect charging equipment.		ADE4 40 D 4407TO
F AR	Maintaining on-board electrical system voltage when performing		AR54.10-D-1127TS
	test and diagnosis work on vehicle		
	and and an analysis of the second sec	(3)	
		During the entire work procedure a	
		sufficiently large voltage supply	
		must be provided for the vehicle's	
		on-board electrical system.	
		Otherwise any undervoltage that occurs may damage the control	
		units.	
		ī	
		Follow the operating instructions	
		for the charger.	
		i	
		Use the charger to ensure that an	
		adequate power supply (min. 12.5 V) is provided for the on-	
		board electrical system battery.	
4	Program 2 additional keys.		
' I≆SI	Service Information: Programming		SI80.57-P-0008A
, Ji	and ordering a replacement key or		
	additional key		
		<u>i</u>	
		Compliance with the DRT Directives and a completely filled	
		out, signed and archived DRT	
		form, where applicable, in	
		combination with the repair order	
		are necessary at all times. When ordering one or more replacement	
		or additional keys, the DRT form	
		must always be filled out in full,	
		signed and archived.	
		Observe the Service Information.	
		<u>i</u>	
		It is absolutely essential to precisely follow the operation steps	
		as described in the vehicle	
		diagnosis system.	
5	Disconnect diagnostic system.		
₩AD			AD00.00-D-2000-06TS
6	Remove charger from vehicle.		ADEA 40 D 4407TC
⊯ AR	Chack		AR54.10-D-1127TS
	Check		
7	Perform function test of additional		
	keys.		

Parts ordering note

Part no.	Designation	Quantity
	Key (see XENTRY Parts Information)	2