News Channel Update |

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Service Campaign Launch Notification		
Retrofit Damping on Front Axle and Replace	DATE: M. 07 0000	
Engine Lining	DATE: May 27, 2022	
MY22 EQS-Class (297 platform)		

IMPORTANT SERVICE CAMPAIGN LAUNCH

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



Vehicle Compliance & Analysis

Service Campaign Launch Notification		May 27, 2022				
Campaign No. :	Campaign Desc. :	Retrofit	Damping on Front Axle and Replace			
2022050012	22P0890002		Engine Lining			
	<u>0</u> Model Year ("MY") 2022		amping on the front axle and replace the rear engine orm) vehicles. The vehicles will be visible and flagged in 7, 2022.			
		Background				
Issue	that axle	on certain MY 2022 E0 and rear engine compa s, it is possible the ele	G"), the manufacturer of Mercedes-Benz, has determined QS-Class (297 platform) vehicles, the damping on the front artment lining do not correspond to current specifications. ctronic drivetrain transmission may result in noise in the			
What We're Doing			vice campaign. An authorized Mercedes-Benz dealer will bing and replace the rear engine compartment lining.			
Parts	The	remedy is available	and can be performed as necessary.			
		Vehicles Affect	red			
Vehicle Model Year(s)	202	2022				
Vehicle Model	EQS	-Class				
	Vehicle Populations					
Total Campaign Populati	on 30					
	Next Steps/Notes					
AOMS/SOMS	A	OMs – This campaign	may generate questions from your dealers.			
			I to maintain a high level of vehicle quality and customer r Assistance Center at 1-800-FOR-MERCEDES.			



Service Campaign Bulletin



Campaign No. 2022050012, May 2022

Service Campaign Bulletin

Service Campaign Bulletin

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model EQS-Class (297 platform)

Model Year 2022

Retrofit Damping on Front Axle and Replace Engine Lining

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz, has determined that on certain MY 2022 EQS-Class (297 platform) vehicles, the damping on the front axle and rear engine compartment lining do not correspond to current specifications. Thus, it is possible the electronic drivetrain transmission may output noise into the cabin. An authorized Mercedes-Benz dealer will retrofit the front axle damping and replace the rear engine compartment lining.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.


Approximately 30 vehicles are affected.

Order No. P-SC-2022050012

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Record

Work Procedure

- 1. Perform power disconnect of high-voltage on-board electrical system.
 - i For basic data, see AR47.70-P-1000EQS.
- 2. Remove rear engine compartment cover (B, Figure 2).
 - i For basic data, see AR61.20-P-1105EQS.
- 3. Retrofit damping (A, Figure 1) in area of power electronics control unit (N147/4) on front axle drive module.
- Before installing the damping, the surface of the power electronics on the front axle drive module must be cleaned.
- 4. Replace rear engine compartment cover (B, Figure 2).






Figure 1

Figure 2

- 5. Perform commissioning of high-voltage on-board electrical system.
 - i For basic data, see AR47.70-P-1000EQS.

Primary Parts Information

Qty.	Part Name	Part Number
1	ENGINE COMPARTMENT COVER	A 297 520 46 00
1	FRONT DAMPING	A 297 682 84 02

Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

iNote: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
02-0883		Retrofit damping on front axle drive module Includes: Replace rear engine compartment cover	0.4
08 900 02	02-2193	Perform power disconnect/commissioning for high-voltage on-board electrical system	0.5

Note: Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.