News Channel Update | Vans Customer Service and Parts

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Service Campaign Notification Model 447 (Metris) Model Year 2022 Retrofit PTC Heater	DATE: August, 2022

IMPORTANT SERVICE CAMPAIGN INFORMATION



Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 770.705.0600



News Channel Update | Vans Customer Service and Parts

Campaign No. :	Campaign			
2022070013	VS2WALUZU	Retrofit PTC Heater		
This is to notify you of the upcoming Service Campaign to Retrofit the PTC Heater on approximately 277 MY22 Mercedes- Benz Metris vans. All affected VINs will be flagged as "OPEN" in VMI.				
		Background		
Issue	Due to global supply cor on certain Mercedes-Be	nstraints the PTC Heater was not installed at the time of manufacturing enz Metris vehicles.		
What We're Doing	MBUSA is conducting a s PTC heater in the affect	service campaign. An authorized Mercedes-Benz Metris dealer will retrofit the ed vehicles.		
Parts	Parts Parts will be available end of August			
		Vehicles Affected		
Vehicle Model Year(s)				
Vehicle Model	Metris, VS20 / Platfor	m 447		
		Vehicle Populations		
Total Vehicles	277			
Dealer Inventory	7			
		Next Steps/Notes		
AOMS/SOMS	AOMS/SOMS Please ensure your dealers have read and understand this notice.			
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction.				

Mercedes-Benz USA, LLC



Service Campaign Bulletin

Campaign No. 2022070013 August, 2022

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model 447 Model Year 2022 Retrofit PTC Heater

Due to global supply constraints the PTC Heater was not installed at the time of manufacturing on certain Mercedes-Benz Metris vehicles. An authorized Mercedes-Benz Metris dealer will retrofit the PTC heater in the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 277 Metris vehicles are affected.

Order No. V-SC-2022070013 This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin


Service Campaign Bulletin

- Model 447.### #4 as of 100002 up to 101441 with code HZ0 (Electric auxiliary heater) with code XM0 (Facelift) Model 447.6##/7## #3 as of 977512 up to 989266
- with code HZ0 (Electric auxiliary heater) with code XM0 (Facelift)

Operation no. of the operation texts or standard texts and flat rates

Category	Op. no.	Operation text	Time	Damage Code	Code
Р	02 0051	Operations: Retrofit PTC booster heater control unit	0.8 hrs	06 991 04	VS2WALUZ U
Р	68 5159	Extra work for: Removing/installing center console on vehicles with digital tachograph (DTCO)	0.1hr	06 991 04	VS2WALUZ U


- 1 Electrical connector
- 2 Bolts
- 3 Cover
- 4 Electrical plug connection



S83.70-A037-03



5	Positive line	6	Protective cover	K40/11	Firewall fuse and relay module
5.2	Ring cable lug with nut	A1	Pin terminal		



5.1 Ring cable lug with nut

<u> </u>	Risk of fire /risk of explosion due to short circuit and escaping oxyhydrogen gas. Risk of (burn) injury caused by caustic burns to eyes, skin and mucous membranes from battery electrolyte/mist, short circuit and arcing. Risk of poisoning caused by swallowing battery electrolyte or absorption of lead through the skin or body orifices. Risk of death due to voltage U >= 30 V AC and U >= 60 V DC.	No fires, sparks, open flames, or smoking. Wear acid-resistant gloves, clothing, and glasses. Pour battery acid only into suitable and appropriately marked containers.	AS54.10-Z-0001-01A
Notice	Information on preventing damage to electronic components due to electrostatic discharge		AH54.00-P-0001-01A
Notice	Notes on battery		AH54.10-P-0001-01A
Notice	Notes on carrying out repair work in the vehicle interior		AH68.00-D-0001-01KOS
4	Check		
1	Check if vehicle is affected by measure.	Affected vehicles: Retrofit PTC booster heater control unit (code: VS2WALUZU)	SM83.70-S-0029-01AAA
22	Remove		
2	Detach ground line of on-board electrical system battery.		
₩ AR			AR54.10-S-0003E
3.1	Remove cover under driver's side instrument panel.	447.### 1# with code LC7 (Front footwell illumination)	AR68.10-S-1500E
AR	Bomovo opvor under possenzer	447 ### 2# with code L CZ (Erest	
3.2	Remove cover under passenger side instrument panel.	447.### 2# with code LC7 (Front footwell illumination)	AR68.10-S-1520E
₩ AR			/ 1.00.10-0-1020L

4.1	Partially remove center console.	Model 447 with code FF1 (Center	
 .		console with stowage	
		compartment) except code FG0	
		(Luxury center console with roller	
		blind) or model 447 with code FF2	
		(Center console with 1 device	
		installation frame) except code	
		FG0 (Luxury center console with	
		roller blind) or model 447 with	
		code FG0 (Luxury center console	
		with roller blind) except code FF1	
		(Center console with stowage	
		compartment) and except code	
		FF2 (Center console with 1 device	
		installation frame)	
₩ AR		Model 447 with code FF1 (Center	AR68.20-S-2000E
		console with stowage	
		compartment) and except code	
		FG0 (Luxury center console with	
		roller blind) model 447 with code	
		FF2 (Center console with 1 device	
		installation frame) except code	
		FG0 (Luxury center console with	
_		roller blind)	AR68.20-S-2000EA
₩ AR		Model 447 with code FG0 (Luxury center console with roller blind)	AR00.20-3-2000EA
		and except code FF1 (Center	
		console with stowage	
		compartment) and except code	
		FF2 (Center console with 1 device	
		installation frame)	
		i	
		Center console does not need to	
		be completely removed.	
4.2	Partially remove trim at vertical	Model 447 except code FF1	
	strut.	(Center console with stowage	
		compartment) and except code FF2 (Center console with 1 device	
		installation frame) and except	
		code FG0 (Luxury center console	
		with roller blind)	
			AR68.00-S-1500E
₩ AR			
		The cover on the vertical strut does	
		not need to be removed	
		completely.	
5	Remove electrical connector (1)	i	
	from heater box.	Do not disconnect electrical	
		connector (1).	
6	Remove screws (2).	i	
		The screws (2) are required when	
		retrofitting the new PTC booster	
		heater control unit (N33/4) and	
		therefore must not be disposed of.	
Ĺ			

[
7	Remove cover (3).	i The cover (3) is no longer required and can therefore be disposed of properly. To do so, observe the applicable legal requirements and specifications of the relevant country.	
8	Remove cover from firewall fuse and relay module (K40/11).		
X	Install		
9	Fit ring cable lug with nut (5.2) of positive line (5) at pin terminal (A1) of firewall fuse and relay module (K40/11) and tighten.		
₩ ^{Ser} GF	Assignment of right footwell firewall fuse and relay module	i Remove protective cover (6) if necessary. The protective cover (6) is no longer required and can therefore be disposed of properly. To do so, observe the applicable legal requirements and specifications of the relevant	GF54.15-S-1256-39TRF
		country. Nm M6	BA00.10-Z-1002-01KOA
10	Install cover at firewall fuse and relay module (K40/11).		
11	Retrofit PTC heater booster control unit (N33/4).	 Install PTC booster heater control unit (N33/4) carefully and uniformly into device installation frame without allowing it to become jammed. This prevents damage. Model 447.### 1# 	
		When doing so, operate brake pedal. Ensure that PTC booster heater control unit (N33/4) is seated correctly in device installation frame.	
12	Fasten PTC booster heater control unit (N33/4) with screws (2).	i For fastening, use the screws (2) of the cover (3) that is no longer required.	
13	Attach electrical connector (1) at heater box.	i Check retaining clips for damage. If the retaining clip is damaged, ↓ Replace damaged retaining clip.	

14	Connect electrical connector coupling (4) at PTC booster heater control unit (N33/4).		
15	Expose strapped-down ground line (7) and positive line (5) if necessary and route correctly.		
16	Attach ring cable lug with nut (7.1) of ground line (7) at PTC booster heater control unit (N33/4) and tighten.	Nm Nut, wiring harness to PTC heater booster	BA54.18-Z-1001-02KOA
17	Attach ring cable lug with nut (5.1) of positive line (5) at PTC booster heater control unit (N33/4) and tighten.	i Remove protective cover (8) if necessary. The protective cover (8) is no longer required and can therefore be disposed of properly.	
		To do so, observe the applicable legal requirements and specifications of the relevant country.	
		Nm Nut, wiring harness to PTC	BA54.18-Z-1001-02KOA
		heater booster	
18.1	Attach center console.	Model 447 with code FF1 (Center console with stowage compartment) and except code FG0 (Luxury center console with roller blind) or model 447 with code FF2 (Center console with 1 device installation frame) and except code FG0 (Luxury center console with roller blind) or model 447 with code FG0 (Luxury center console with roller blind) and except code FF1 (Center console with stowage compartment) and except code FF2 (Center console with 1 device installation frame)	
₩ F AR		Model 447 with code FF1 (Center console with stowage compartment) and except code FG0 (Luxury center console with roller blind) or model 447 with code FF2 (Center console with 1 device installation frame) and except code FG0 (Luxury center console with roller blind)	AR68.20-S-2000E
₩ F AR		Model 447 with code FG0 (Luxury center console with roller blind) and except code FF1 (Center console with stowage compartment) and except code FF2 (Center console with 1 device installation frame)	AR68.20-S-2000EA

18.2	Attach trim at vertical strut.	Model 447 except code FF1 (Center console with stowage compartment) and except code FF2 (Center console with 1 device installation frame) and except code FG0 (Luxury center console with roller blind)	
₩FAR			AR68.00-S-1500E
19.1	Install cover under driver's side instrument panel.	Model 447.### 1# with code LC7 (Front footwell illumination)	AR68.10-S-1500E
19.2	Install front passenger side cover below instrument panel.	Model 447.### 2# with code LC7 (Front footwell illumination)	AR68.10-S-1520E
₩ AR			AR00.10-3-1320E
20	Connect ground line of on-board electrical system battery.		
₩ĨAR			AR54.10-S-0003E
	Installing		
21	Install vehicle diagnosis system.		
A D	Connect STAR DIAGNOSIS and read out fault memory		AD00.00-S-2000-04E
		i Always make sure that XENTRY Diagnosis is updated to the latest version. i It is essential to follow the operation steps in the diagnostic system.	
	Perform quick test		
22	Perform quick test Perform quick test and delete fault code B10BB87 in air conditioning system control and operating unit (front & rear AAC) (S98).	i Do not yet remove vehicle diagnosis system. i For this, select the following option in the diagnostic system: Control units view → S98 - Air conditioning system (AAC) (code: HH4, HH9, H13, HI1) → Start quick test If further fault codes are stored in the fault memory, ↓ they must be processed in a separate job and must not be invoiced as part of this service measure.	

4	Check		
23	Check PTC heater booster control unit (N33/4) for proper operation.	 i For this, select the following option in the diagnostic system: Actuations → N33/4 (Electric PTC booster heater) i It is absolutely essential to precisely follow the operation steps as described in the vehicle diagnosis system. i The "Ignition ON" requirement must be satisfied. Check the status of the associated actual values in the percentage display. To do so, move the displayed bar in the display of the diagnostic system to four different values (from 0% to 100%). Compare the set values with the percentage of the "Actual values" column. Functionality is ensured if the set values in the bar match the values in the "Actual values" 	
	Bamaya	column.	
04	Remove		
24	Remove vehicle diagnosis system from vehicle.		

$\ensuremath{\mathbb{N}}\xspace_{\ensuremath{\mathbb{N}$

Number	Designation			8.8	10.9
BA00.10-Z-1002-01KOA	M6	Galvanized	Nm	9	13
		Phosphated	Nm	9	12

Nm Headless screws/bolts: screws/bolts and nuts, coarse-pitch thread

Number	Designation			12.9
BA00.10-Z-1002-01KOA	M6	Galvanized	Nm	16
		Phosphated	Nm	14

Nm Wiring harness

Number	Designation			Model 447, 448
BA54.18-Z-1001-02KOA	Nut, wiring harness to PTC heater booster	M6	Nm	8
		M8	Nm	16

Parts ordering note

Part no.	Designation	Quantity
A 447 830 08 61	PTC heater booster control unit	1