News Channel Update | Vans Customer Service and Parts

TO: Mercedes-Benz Dealers, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Service Campaign Notification Model 907 Sprinter Model Years 2019-2021 <u>*UPDATED*</u> Replace Front Door Check	DATE: June, 2023

IMPORTANT SERVICE CAMPAIGN INFORMATION



Mercedes-Benz

UPDATED
DOOR CHECKS MUST BE REPLACED

Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 770.705.0600



News Channel Update | Vans Customer Service and Parts

Campaign No. :	Campaign Desc. :	Bonlace Front Door Chock	
2022100014	VS3TU72EST	Replace Front Door Check	
This is to notify you of th	e upcoming Service Campaig	n to replace the front door check on approximately 10,091 MY 2019-2021	
Mercedes-Benz Sprinter	vans. All affected VINs will be	flagged as "OPEN" in VMI.	
		Background	
Issue	that the door check might k that plastic deformation in	5"), the manufacturer of Mercedes-Benz Sprinter vehicles, has determined become deformed in certain vehicles due to a specific usage profile, and the door shell and the hinges might also occur. sible that the driver's door may be more difficult to close.	
What We're Doing	An authorized Mercedes-Benz dealer will replace the existing door check with an optimized version. If damage is present on front door and fender, the dealer will make necessary repairs.		
Parts	Parts are available.		
	-	Vehicles Affected	
Vehicle Model Year(s)	2019-2021		
Vehicle Model	907 Sprinter		
		Vehicle Populations	
Total Vehicles	10,091		
Dealer Inventory	10* Used Car Inventory		
	N	lext Steps/Notes	
AOMS/SOMS	Please ensure your dealers	have read and understand this notice	
While we regret any		e, MBUSA are determined to maintain a high level of vehicle quality and customer satisfaction.	

Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 770.705.0600



Campaign No. 2022100014 November, 2022

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model 907 Sprinter Model Years 2019-2021 Replace Front Door Check

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz Sprinter vehicles, has determined that the door check might become deformed in certain vehicles due to a specific usage profile, and that plastic deformation in the door shell and the hinges might also occur. As a consequence, it is possible that the driver's door may be more difficult to close.

An authorized Mercedes-Benz dealer will replace the existing door check with an optimized version. If damage is present on front door and fender, the dealer will make necessary repairs.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 10,091 Sprinter vehicles are affected.

Order No. V-SC-2022100014 This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.


Service Campaign Bulletin

Service Campaign Bulletin

Model 907 with code Z3A (Amazon customer) with code ZU8 (National version for USA)

Operation no. of the operation texts or standard texts and flat rates

Category	Op. no.	Operation text	Time	Damage Code	Code
L	02 0350	Operations: Check door check, fender and front door	0.2 h	72 902 03	VS3TU72ES T
L	02 0351	Operations: Replace door check and lower hinge of front door (after check)	1.6 h	72 902 03	VS3TU72ES T
L	02 2726	Operations: Disconnect/connect ground line of on- board electrical system battery (when working on veh.)	0.2 h	72 902 03	VS3TU72ES T
L	02 0352	Operations: Replace front door (after check)	2.1 h	72 902 03	VS3TU72ES T
L	02 0354	Operations: Extra work for: Replace front door on veh. with code T75	0.3 h	72 902 03	VS3TU72ES T
L	02 0353	Operations: Replace fender (after check)	0.7 h	72 902 03	VS3TU72ES T
L	12 1702	Operations: Paint fender (when replacing fender)	1.3 h	72 902 03	VS3TU72ES T
L	12 1703	Paint front door (when replacing front door)	2.4 h	72 902 03	VS3TU72ES T




D72.10-A009-79

Example for damage at front door and fender

Front door 1

2 Fender



Example for damage at front door reinforcement

Front door 1.1 Reinforcement

Shown on driver side

- Front door 1
- 3 Door catch
- 4 Hinge

1



3

Door catch

D72.10-A008-76

Important!

On affected vehicles, increased loads on the door check (3) may cause damage at the front door (1) or fender (2).

If the front door (1) or fender (2) is replaced as a result of damage, representative pictures of the affected component parts must be taken and filed in a tamperproof manner with the repair order.

We also ask to you inform the customer that the front door must only be opened **after the vehicle has come to a standstill**. Otherwise, the existing damage profiles may reoccur.

∱ Warning	Risk of injury caused by fingers being jammed or pinched when removing, installing or aligning hoods, doors, trunk lid/rear-end door or sliding roof.	No parts of the body or limbs should be within the operating area when the components are moving.	AS00.00-Z-0011-01A
A Caution	Risk of injury caused by scraping or cutting body parts on sharp vehicle parts	Always wear protective gloves when working on or near sharp and non-deburred vehicle parts.	AS00.00-Z-0017-01A
		Deburr repair panels.	
Notice	Notes on carrying out repair work in the vehicle interior		AH68.00-D-0001-01KOS
4	Check		
1	Check whether vehicle is affected by measure.		
2 Maran	Check front door (1) for damage.	 i Only damage resulting from contact with the corresponding fender (2) is to be taken into consideration. See the example picture above with regard to this. If front door (1) is damaged, ↓ replace front door (1). Disassembling and assembling front door i Before replacing front door (1), take representative pictures of the affected areas and file in a tamperproof manner with the repair order. i Observe operation steps 5–6 of this measure. 	AR72.10-D-0510TS

2	Chaok fonder (2) for domost]
3	Check fender (2) for damage.	i Only damage resulting from contact with the corresponding front door (1) is to be taken into consideration.	
		See the example picture above with regard to this.	
		If fender (2) is damaged,	
⊯≊AR		replace fender (2). Remove/install front fender	AR88.10-D-1005TS
		i Before replacing fender (2), take representative pictures of the affected areas and file in a tamperproof manner with the repair order.	
4	Check reinforcement (1.1) of front door (1).	i Check whether cracks are visible at reinforcement (1.1).	
		Take representative pictures of the affected areas and file in a tamperproof manner with the repair order.	
		If cracks are present,	
₩ AR		replace front door (1). Disassembling and assembling front door	AR72.10-D-0510TS
		i Before replacing front door (1), take representative pictures of the affected areas and file in a tamperproof manner with the repair order.	
		i Observe operation steps 5–6 of this measure.	

	Replace		
<u>∧</u> Danger	Risk of explosion caused by paint vapors igniting. Risk of poisoning caused by inhaling paint vapors. Replace lower hinge (4) of front	No smoking! No open fire! Use respiratory protection, protective clothing, gloves, safety glasses and protective skin cream. Ensure that the area is well ventilated.	AS98.00-Z-0002-01A
Notice	door (1). Notes on paintwork repairs		AH98.00-P-9408-02A
₩ĨAR		 i Paint new lower hinge (4) in vehicle color. i Only use paints approved by the manufacturer. See guidelines for paint technology 	AR72.10-D-2662TS
		in the workshop portal.	
6 ⊯~AR	Replace door check (3).	i Inform the customer that the front door must only be opened after the vehicle has come to standstill.	AR72.10-D-2100TS
	SmallRepair		
<u>∧</u> Danger	Risk of explosion caused by paint vapors igniting. Risk of poisoning caused by inhaling paint vapors. Rectify paint damage at front door	No smoking! No open fire! Use respiratory protection, protective clothing, gloves, safety glasses and protective skin cream. Ensure that the area is well ventilated. If paint damage is present.	AS98.00-Z-0002-01A
7	(1) or at fender (2).	n paint damage is present.	
Notice	Notes on paintwork repairs	 i Only damage that is caused by the two component parts coming into contact is to be taken into consideration. i For this, use SmallRepair. Before painting, take representative pictures of the affected areas and file in a tamperproof manner with the repair order. i Only use paints approved by the manufacturer. See guidelines for paint technology in the workshop portal. 	AH98.00-P-9408-02A

Parts ordering note

Part no.	Designation		
	Replace door check parts		
A 910 720 59 00	Door catch	1	
N 000000 008272	Nut	2	
N 000000 004829	Screw	1	
A 910 723 02 00	Door check seal	1	
A 910 720 14 00	Bottom hinge	n. B.	
N 910105 008005	Screw	2	
A 000 990 60 37	Screw	2	
	Replace front door parts		
A 910 720 24 00	Driver's door	n. B.	
A 907 727 00 00	Sealing foil	n. B.	
A 910 727 00 00	Inner door panel seal (on veh. except code XM4 (Acoustic package))	n. B.	
A 907 727 29 00	Inner door panel seal (on veh. with code XM4 (Acoustic package))	n. B.	
A 906 682 05 09	Insulation (on veh. with code H04 (Heat insulation for driver compartment))	n. B.	
A 639 602 03 80	Damping material	n. B.	
N 910002 003108	Rivet on veh. with code T75 (Grab handle for driver and front passenger entrance)	2	
A 000 997 73 86 9051	Stop plug (on veh. with code T75 (Grab handle for driver and front passenger entrance))	2	
A 000 990 47 37	Rivet nut (on veh. with code T75 (Grab handle for driver and front passenger entrance))	2	
	Replace fender parts		
A 910 881 00 00	Fender	n. B.	
A 910 885 04 00	Bumper bracket	n. B.	
	Miscellaneous parts		
A 124 990 04 92	Expansion rivet	n. B.	
A 910 991 00 00	Mounting clip	n. B.	
A 000 991 86 98	Mounting clip	n. B.	