News Channel Update |

Vehicle Compliance & Analysis

MY14-20 S-Class (217 and 222 platform)			
Check Front Axle Tension Strut Pilot Bushings	DATE: June 23, 2023		
RE: Service Campaign Launch Notification			
Sales Managers, Service Managers, Parts Managers Compliance and Analysis, Engineering Services			
TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle		

IMPORTANT SERVICE CAMPAIGN LAUNCH

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES (1-800-367-6372).

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



Vehicle Compliance & Analysis

Service Campaign Launc		lotification	June 23, 2023			
Campaign No.:	Campaign Desc. :	Che	ck Front Axle Tension Strut Pilot			
2023050005	22P3390024					
This is to notify you of the Service Campaign Launch to check the front axle tension strut pilot bushings on <u>56</u> Model Year ("MY") 2014-2020 S-Class (217 and 222 platform) vehicles. The vehicles will be visible and flagged in VMI as "OPEN" on June 23, 2023.						
		Background				
Issue What We're Doing		Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2014-2020 S-Class (217 and 222 platform) vehicles, the incorrect pilot bushings may have been installed in the front axle tension struts. It is possible that noises and an increased wear of the pilot bushings may occur.				
			vice campaign. An authorized Mercedes-Benz dealer will n the front axle tension struts, and replace if necessary.			
Parts	The	e remedy is available	and can be performed as necessary.			
		Vehicles Affect	ed			
Vehicle Model Year(s)	201	2014-2020				
Vehicle Model		S-Class (217 and 222 platform)				
		Vehicle Populati	ons			
Total Campaign Populat	ion 56	56				
		Next Steps/No	tes			
AOMS/SOMS		AOMs – This campaign	may generate questions from your dealers.			
			I to maintain a high level of vehicle quality and customer Assistance Center at 1-800-FOR-MERCEDES.			



Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin



Campaign No. 2023050005, June 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model S-Class (217 and 222 platform)

Model Year 2014-2020

Check Front Axle Tension Strut Pilot Bushings

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2014-2020 S-Class (217 and 222 platform) vehicles, the incorrect pilot bushings may have been installed in the front axle tension struts. It is possible that noises and an increased wear of the pilot bushings may occur. An authorized Mercedes-Benz dealer will check the pilot bushings on the front axle tension struts, and replace if necessary.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 56 vehicles are affected.

Order No. P-SC-2023050005

Check Front Axle Tension Strut Pilot Bushings




Figure 1






Figure 2

Check/test procedure

- 1. Remove tension struts (1, Figure 1) of front axle on both sides.

 i For basic data, see AR33.15-P-0160LF.
- 2. Check diameter (A, Figure 2) of pilot bushing (2, Figure 2) on both sides.
 - a. Diameter (A) less than 50 mm: Perform work procedure on affected side.
 - b. Diameter (A) greater than or equal to 50 mm: End measure.

Work procedure

Replace affected tension strut of front axle.
 For basic data, see AR33.15-P-0160LF.

2. Assemble in reverse order.

Primary Parts Information

Qty.	Part Name	Part Number
As required (1)	Right tension strut	A 217 330 52 00 28
As required (1)	Left tension strut	A 217 330 51 00 28
2	Nut	A 005 990 24 50
2	Nut	A 005 990 47 50
4	Spacer disk	A 220 333 00 76 02
2	Nut	N 000000 008261
2	Screw	N 308765 014012

Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	
33 900 24	12-1681	Operations: Check front axle tension strut pilot bushing on both sides Includes : Remove/install 2 wheel and tire assemblies, remove/install lower engine compartment lining, tension strut of front axle (on both sides)	2.0
	12-1682*	Operations: Replace affected tension strut of front axle (after check)	0.1

Invoice operation item only once for each workshop order.

Note: Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.