

# WORK DESCRIPTION FOR FIELD MEASURE

Code: 24P5498824

Version: 2.0

## Perform SCN coding in EIS control unit

Model 192

---

- i** • Always use the **latest** XENTRY Diagnosis software release with all available add-ons.
  - Make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
  - Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
  - If XENTRY Diagnosis is already connected to the vehicle, start with **Work Procedure Step 2**.
- i** If two or more software updates or SCN codings are performed during one workshop visit, operation items 02-4762 and 02-5058 may be invoiced **only once for each workshop order**.

### Work Procedure

1. Connect XENTRY Diagnosis.
  2. Perform SCN coding in **EIS** control unit.
    - i** To do this, select menu item "Quick test view → **N73/3 – electronic ignition lock (EIS)** → Adaptations → Control unit update → Updating of SCN coding".
    - i** Then follow the user guidance in XENTRY Diagnosis.
  3. Disconnect XENTRY Diagnosis.
- 

### Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9446	Perform SCN coding in <b>EIS</b> control unit (with XENTRY Diagnosis connected)	0.1 h	54 988 24
02-4762*	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1 h	54 988 24
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	54 988 24

---

\* Operation item may be invoiced only once for each workshop order.