

WORK DESCRIPTION FOR FIELD MEASURE

Code: 20P354017

Version: 2.0

Replace trim of left and right thrust arm on the rear axle

Model 223

Work procedure

1. Lift vehicle with vehicle lift.
 For basic data, see AR00.60-P-1006A.
2. Replace trim (A, figure 1) of left and right thrust arm on the rear axle.




Figure 1

Parts

Quantity	Designation	Part no.
1	Left trim	A 223 352 63 01
1	Right trim	A 223 352 64 01
4	Expansion rivet	A 001 991 05 40
2	Mounting bracket	A 223 352 62 01

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-1862	Replace trim for left and right thrust arm of the rear axle	0.3 h	35 940 17

Mercedes-Benz
Global Service & Parts