

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Service Campaign Notification Model 907 (Sprinter) Model Year 2021 Replace Vehicle Emission Control Information Label	DATE: July, 2022

IMPORTANT SERVICE CAMPAIGN INFORMATION



Mercedes-Benz



Campaign No. :	Campaign	Replace Vehicle Emission Control Info Label (VECI)
2022070008	VS3LABECI	
<p>This is to notify you of the upcoming Service Campaign to replace the Vehicle Emission Control Information Label (VECI) on approximately 72 MY21 Mercedes-Benz Sprinter vans. All affected VINs will be flagged as “OPEN” in VMI.</p>		
Background		
Issue	Mercedes-Benz AG, the manufacturer of Mercedes-Benz Sprinter vehicles, determined that in certain vehicles, the VECI label does not correspond to current production configuration.	
What We’re Doing	MBUSA is conducting a service campaign. An authorized Mercedes-Benz Sprinter dealer will replace the Vehicle Emission Certification Information (VECI) label on the affected units.	
Parts	Parts are available.	
Vehicles Affected		
Vehicle Model Year(s)	Model Year 2021	
Vehicle Model	Sprinter, VS30 / Platform 907	
Vehicle Populations		
Total Vehicles	72	
Dealer Inventory	0	
Next Steps/Notes		
AOMS/SOMS	Please ensure your dealers have read and understand this notice.	
<p>While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction.</p>		



Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2022070008 July, 2022

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 907 Model Year 2021
Replace Vehicle Emissions
Control Information label**

MBAG, the manufacturer of Mercedes-Benz Sprinter vehicles, determined that in certain vehicles, the VECI label does not correspond to current production configuration.

An authorized Mercedes-Benz Sprinter dealer will replace the Vehicle Emission Certification Information (VECI) label on the affected units.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately **72 MB** Sprinter vehicles are affected.


Order No. V-SC-2022070008 This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

**Model 907 with engine 642
with code ZU8 (National version for USA)**

Operation no. of the operation texts or standard texts and flat rates

Category	Op. no.	Operation text	Time	Damage Code	Code
L	02 0616	Operations: Replace information label for certification for exhaust gas	0.2 hrs	58 917 18	VS3LABECI



D00.00-A128-78

1 Information label

⚠ Warning	Risk of injury. Skin or eye injuries may result when handling hot or glowing objects.	Wear protective gloves, protective clothing and safety glasses, if necessary.	AS00.00-Z-0002-01A
Notice	Notes on carrying out repair work in the vehicle interior		AH68.00-D-0001-01KOS
◀	Check		
1	Check whether the vehicle is affected by the measure.		

