

WORK INSTRUCTION FOR 2016060016

This campaign affects only the following Vehicles:

4JGDA0EB7FA425951 4JGDA0EB7FA425951
4JGDA0EB6FA425956 4JGDA0EB6FA425956
4JGDA0EB8FA425957 4JGDA0EB8FA425957
4JGDA0EB1FA425962 4JGDA0EB1FA425962
4JGDA0EB9FA425966 4JGDA0EB9FA425966

Code: 1602P09A29

Version: 2.0

Replace charge air hose between charge air cooler and turbocharger

Model 166 with OM651

Work procedure

1. Replace charge air hose (A) between charge air cooler and turbocharger (Figure 1).
 - i** Lower engine compartment paneling is not necessary, contrary to the AR-document.
 - i** For basic data, see AR09.41-P-8619CD.



Figure 1

Parts

Quantity	Designation	Part No.
1	Charge air hose	A 166 528 04 82 05

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no.
02-9274	Replace charge air hose between charge air cooler and turbocharger	0.3 h	09 950 32

Mercedes-Benz
Global Service & Parts