

# Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2021080002, October 2021

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model GLE-Class, GLS-Class (167 platform)**  
**Model Year 2021**

**Add Tool for Wheel Hub Cover**

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz, has determined that on certain MY 2021 GLE-Class and GLS-Class (167 platform) vehicles, the tool for the wheel hub cover may be missing. MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will check for the tool, and install if necessary.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 882 vehicles are affected.

Order No. P-SC-2021080002

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Record

# Service Campaign Bulletin

**Add tool for wheel hub cover**Model 167

---

**Work Procedure**

1. Add tool for wheel hub cover to the trunk, under the load compartment cover.

**i** There is no separate slot in the trunk.

---

**Primary Parts Information**

Qty.	Part Name	Part Number
1	Wheel hub cover tool	A 000 581 00 00

---

**i** **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

**Warranty Information**

Damage Code	Operation Number	Description	Labor Time (hrs.)
58 902 02	02-0565	Add tool for wheel hub cover.	0.1

**i** **Note:** Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.