










	Notes on programming control units		AH54.21-P-0001-03Z
	Check		
1	Check whether vehicle is affected by measure.	 <p>For authorized Mercedes-Benz service partners, only the entry in the Extended VEGA Application (EVA) system, in the "Current" tab, is decisive. There is no need to also check the affected vehicles in the workshop information system (WIS) or vehicle list.</p>	
	Update software		
2  AD	Connect diagnostic system.	 <p>Always use the latest XENTRY Diagnosis software release.</p>  <p>It is absolutely essential to precisely follow the operation steps as described in the vehicle diagnosis system.</p>	AD00.00-D-2000-06TS
3  AR	Connect charging equipment. Maintaining on-board electrical system voltage when performing test and diagnosis work on vehicle	 <p>During the entire work procedure a sufficiently large voltage supply must be provided for the vehicle's on-board electrical system. Otherwise any undervoltage that occurs may damage the control units.</p>  <p>Follow the operating instructions for the charger.</p>  <p>Use the charger to ensure that an adequate power supply (min. 12.5 V) is provided for the on-board electrical system battery.</p>	AR54.10-D-1127TS

4	Update software for CDI control unit (N3/28 – Engine electronics 'CDI61NFZ' for combustion engine 'OM642' (CDI)).	<p>i It is absolutely essential to precisely follow the operation steps as described in the vehicle diagnosis system.</p> <p>i To do this, select the following menu items: Control units view → N3/28 – Engine electronics 'CDI61NFZ' for combustion engine 'OM642' (CDI) → Special procedures → Service measure "Exhaust gas aftertreatment"</p>	
5	Disconnect diagnostic system.		AD00.00-D-2000-06TS
6	Remove charger from vehicle.		AR54.10-D-1127TS
7	Fill out campaign label (1) and attach to air filter housing (2).	<p>Only applies for vehicles in State of California.</p> <p>! Bonding surface must be absolutely free of dust and grease. Otherwise, a sufficient degree of adhesion cannot be assured.</p> <p>i To do so, enter 6-digit campaign number, dealer code and date. Cleaner</p>	BR00.45-Z-1025-04A
8	Fill out certificate and hand over to customer.	<p>Only applies for vehicles in State of California.</p> <p>i Apply number from campaign label (1).</p>	

Repair materials

Number	Designation	Order number
BR00.45-Z-1025-04A	Cleaner	A 005 989 19 71

Parts ordering note

Part no.	Designation	Quantity
A 000 584 54 13	Campaign label (California only)	1
A 000 584 42 14	Certificate (California only)	1