

# WORK DESCRIPTION FOR FIELD MEASURE

Code: 23P6892005

Version: 2.0

**Check additional cushions for leg rest in rear passenger compartment for soiling or discoloration and replace if necessary**

Model 223 Maybach Haute Voiture

## Check/test procedure

1. Check whether the additional cushions for the leg rest in the rear passenger compartment of the vehicle are soiled/discolored.

**i** The additional cushions for the leg rest in the rear passenger compartment can be installed or in the black transport bag in the trunk.



Figure 1

- a. Additional cushion(s) for leg rest in rear passenger compartment **is/are** soiled/discolored: Carry out **work procedure**.
- b. Additional cushion(s) for leg rest in rear passenger compartment **is/are not** soiled/discolored: **End measure**.

i.o



Figure 2, OK condition

n.i.o



Figure 3, not OK condition

n.i.o



**Work procedure**

1. Enclose additional cushion(s) for leg rest in rear passenger compartment according to vehicle version.

**Parts**

Quantity	Designation	Part no.
As required*	Additional cushion for leg rest (calf support cushion)	A 223 920 48 06 1D13

**i** Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

**Operation text and flat rate**

Operation no.	Operation text	Flat rate	Accounting no./ damage code
12-1993	Check additional cushion for leg rest in rear passenger compartment for discoloration	0.1 h	68 920 05
12-1994*	Replace additional cushion(s) for leg rest in rear (after check)	0.1 h	68 920 05

\* Operation item must be repeated as often as required

Mercedes-Benz  
Global Customer Service & Parts