WORK DESCRIPTION FOR FIELD MEASURE

Code: 21P5891127 **Version: 2.0**

Supply printed operator's manual; replace if necessary

Model 290 with code 801

i •	Code 801	corresponds to	modification y	ear 2020/
-----	----------	----------------	----------------	-----------

- Code 549 corresponds to CONNECT 20 HIGH (NTG6)
- Code 548 corresponds to CONNECT 20 MID (NTG6)

Scope of work

i Supply printed operator's manual; replace if necessary

1. Check whether the operator's manual is in the vehicle document wallet and what version it is.

i If **no** operator's manual is found, a printed operator's manual must be inserted in the vehicle document wallet.

If there is a printed operator's manual, compare it with the parts table.

Parts scope - Printed operator's manual

Quantity	Part no.	Designation	Language	Code
As required				
(1)*	A 290 584 09 02	OPERATOR'S MANUAL A-HIGH USA CAN A-2021	English USA	801+549+12B
As required				
(1)*	A 290 584 97 01	OPERATOR'S MANUAL A-MID USA CAN A-2021	English USA	801+548+12B

^{*} The operator's manuals must be procured through the usual replacement part ordering channels.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9471	Check operator's manual, supply if necessary	0.1 h	58 911 27

Mercedes-Benz Global Service & Parts